ELECTROSTATIC SPRAYERS CHECK LIST




Before You Spray ...

CHECK YOUR GROUNDING ___


1. Ground everything in the immediate Spraying Area including Pump or Tank




2. Ground the Generator or Control Cabinet



3. Ground the target to the booth or building structure



4. Clean all component hooks, fixtures & mounting bars frequently



CHECK YOUR CLOTHING

1. Wear Ransburg Conductive Gloves



2. Wear Anti-static Conductive Footware (R<100 M Ω .)



3. Wear Anti-Static Overalls (R<100 MΩ.)



4. Wear the Correct Mask type for the paint being sprayed




PROTECT THE SYSTEM -

1. Use a Ransburg Gun Cover



2. Protect the Hoses from spray contamination (Optional)




2. Check the Air Cap, Fluid

in good condition

Nozzle & Electrode are

3. Use genuine Ransburg Conductive Air & Fluid




4. Never immerse the gun in



CHECK THE SYSTEM


1. Check all cable connections are secure




5. Check the Fluid Nozzle is

secure & leak free

6. Check for the correct Air &




3. Check the Display is operational when switched on (Classic & Cascade)




7. Clean Gun exterior to prevent contamination



4■ When spraying, check the HV, HV Range, and the Local HV Control lights are ON. Also the µA value and LEDs are in the Green or Amber (Classic & Cascade)



8. Check the Lights on the gun (Solo & Cascade) during spraying



USA/CANADA www.ransburg.com **BRAZIL**

UNITED KINGDOM www.finishingbrands.com.eu **FRANCE** www.binks.com.br www.finishingbrands.com.eu **MEXICO GERMANY** www.binks.com.mx www.finishingbrands.com.eu

CHINA www.finishingbrands.com.cn **JAPAN** www.finishingbrands.com.jp **AUSTRALIA** www.finishingbrands.com.au

Ransburg